

# MAP 1000: Alternate Serial/Parallel Adapter - Parallel Port

Symptom Explanation	Conditions That Could Cause This Symptom
You have entered this MAP because you received a 10XX error code, you suspect an Alternate Serial/Parallel Adapter - Parallel Port problem, or you have been directed here from another MAP.	<ul style="list-style-type: none"><li>The adapter assigned as the "Alternate Parallel Port" is failing.</li></ul>

Ensure the following conditions exist:

1. An adapter is set for "Primary Parallel Port" operation.
2. A second adapter with a parallel port is installed and is set for "Alternate Parallel Port" operation.

## 001

- Power off the system.
- Disconnect the printer cable if it is attached to the parallel port set for alternate operation.
- Insert the Advanced Diagnostics diskette into drive A.
- Run the Alternate Serial/Parallel - Parallel Port tests. Use the **(RUN TESTS ONE TIME)** option.
- Follow the instructions on the screen. Do not power off the system during this test.

**Note:** Use wrap plug (IBM Part 8529228) when instructed to install the wrap plug.

(Step 001 continues)

**001** (continued)

**DID YOU RECEIVE AN ERROR MESSAGE?**

Yes    No

**002**

You have successfully completed the Advanced Diagnostic tests. If you suspect an intermittent problem, start an error log. If you need instructions, refer to the Reference manual.

**003**

Replace the Alternate Serial/Parallel Adapter.

---